



Introductions

Arnold and Scangas Architects

Laz Scangas, Principal

Bread Loaf Corporation

Paul Wyncoop, Client Service Manager











Arnold & Scangas Architects

Arnold and Scangas is an architectural firm located in downtown St. Albans, Vermont. For the last 20 years, we have specialized in restoring historically significant buildings, especially those located in Vermont downtowns. The firm also works with local non-profits in designing affordable housing projects for the community, with many of those being in historic buildings.











Bread Loaf Corporation

Bread Loaf Corporation is a Planning, Architecture and Construction firm, headquartered in Middlebury with a staff of 90 professionals including:

- Sustainable Designers
- LEED Accredited Professionals
- Mechanical, Electrical, Plumbing &
 Fire Protection Project Managers

- Architects
- Construction Managers
- Cost Estimators
- Engineers
- Historic Preservationists



Workshop Overview:

- Introduction
- Challenge #1 Overcoming Disaster
- Challenge #2 Meeting Preservation Standards
- Challenge #3 Life Safety and Building Access
- Challenge #4 Energy Efficiency
- Conclusions and Questions





















Introduction – Historical Context

- Brooks House in Brattleboro
- Town of Harford Town Offices
- UVM Alumni House in the Burlington Hill District
- Arthurs Department Store in Morrisville
- Stanislaus School in West Rutland
- Watkins Avenue School in Rutland

All Buildings are important, contributing historic structures that are in, or near established downtowns





Builders



Brooks House completed 1871, designed by the Worcester, Mass. architectural firm of E. Boyden and Son for George Brooks to replace hotel on same site which had burned.







Historical Context - Main Street Brattleboro and Brooks House - 1870's






Builders



Historical Context - 1950's: Changing times and demographics, changes to building usage



- Central location
- Many years of multiple and diverse tenants
- Often Downtown residential units
- Visual icon for downtown
- Multiple Entries and access
- Sites serve multiple functions:
 parking; open space; access to
 multiple buildings; informal meeting
 space
- Buildings with stories and history



Context of Brooks House in Downtown





Architect Planners Builders



Historical Context – Historic View Looking East





Planners Builders



Historical Context - 1977: Arthur's Department Store





Planners Builders




Historical Context - 1978: Arthur's Department Store












Historical Context – Stanislaus School





Planners Builders



Historical Context – Stanislaus Convent





"Architects Planners Builders







Historical context: Watkins Schools built in neighborhoods







Historical Context – Edward Wells Residence, Burlington





Introduction – Building type/structural considerations

- Multi- story brick bearing walls with some steel and stone structure
- Wood Framed interiors
- Foundation: Stone walls with granite piers
- Some buildings with Cast Iron columns, large storefronts at first floor
- Terracotta/cast stone detailing
- Slate, metal and membrane roofing
- Mostly uninsulated
- Multiple renovations over the years





Planners Builders



Overview of Structure/Construction





Architects Planners Builders




Overview of Structure/Construction













Overview of Structure/Construction - Town of Hartford











Planners Builders



Overview of Structure/Construction or Lack of Construction-Arthur's Department Store





Architects Planners Builders



Overview of Structure/Construction Stanislaus School

Overview of Structure/Construction Stanislaus Convent













Challenge #1: Overcoming Disaster

- Fire and Water Damage
- Hazardous Materials
- Structural Deficiencies
- Vacancy





Challenge #1: Overcoming Disaster

Fire and Water Damage



Brooks House Fire Damage - Confined to certain areas, water damage throughout





Planners Builders



Brooks House, post fire







Brooks House - August 29, 2011






"Architects Planners Builders

Failure of Existing fire prevention system

- Outdated wiring and fire alarm system
- Limited fire blocking in walls
- Minimal floor to floor separation
- No sprinkler in attic areas









Architects Planners Builders

Challenge #1: Overcoming Disaster

Fire and Water Damage







Arthur's Fire Damage - Confined to certain areas





Challenge #1: Overcoming Disaster

Fire and Water Damage



Town of Hartford – November 4, 1927





Builders





Town of Hartford Municipal Building - Basement work to allow water entry





Planners Builders



Town of Hartford – Installation of flood water louvers







Town of Hartford – Flood louvers within existing fenestration pattern





Challenge #1: Overcoming Disaster

- Hazardous Materials
 - Mold
 - Lead Paint
 - Bird/Animal Waste
 - Asbestos and Other materials







Architects Planners Builders

Hazardous Materials



Mold and mold abatement





Architects Planners Builders

Hazardous Materials







Stanislaus School Mold and mold abatement





Moisture Control



Brooks House - Moisture control at storefronts



Builders

Moisture Control



Basement moisture mitigation







Architects Planners Builders

Moisture Control



Basement moisture mitigation









Stanislaus School Moisture Control

Basement moisture mitigation









"Architects Planners Builders



Stanislaus School Moisture Control

Basement moisture mitigation









Architects Planners Builders

Watkins School Moisture Control Basement moisture mitigation













Architects Planners Builders

Hazardous Abatement



Brooks House - Lead Paint





Builders

Hazardous Abatement











Architects
Planners
Builders

• Hazardous Abatement

Pooping on people In 12 easy lessons.







"Architects Planners Builders

Arthur's Hazardous Abatement













Planners Builders

Hazardous Abatement








'Architects Planners Builders

Arthur's Hazardous Abatement











Builders

Challenge #1: Overcoming Disaster

Structural Deficiencies





Brooks House - Structural damage/changes over time





Builders

• Structural Deficiencies





Brooks House - Unsympathetic alterations over time/Building movement





Planners Builders

Structural Deficiencies



Brooks House - Structural rework





Architects Planners Builders



Brooks House - Steel added to upgrade structure to modern code requirements

Architects Planners Builders

Structural Upgrades





Wood reinforcing at Mansard Roof and Penthouse





Architects Planners Builders

Structural Upgrades



Steel, wood and masonry work - Brooks House







Planners Builders



Town of Hartford







Town of Hartford Basement Beam Reinforcing





Architects Planners Builders



Town of Hartford- Attic Structural Reinforcement

Architects Planners Builders

Arthur's Structural Upgrades











'Architects Planners Builders

Challenge #1: Overcoming Disaster

Structural Deficiencies





Watkins School - Structural damage over time due to roof leak





Architects Planners Builders

Challenge #1: Overcoming Disaster

Vacancy











Challenge #2: Meeting Preservation Standards


- Why Preserve?
- Important Features- Exterior
- Important Features- Interior
- Challenges-
 - Brick Repair and Restoration
 - Architectural Detail in Wood
 - Windows and Storefront
 - Flashing and Roofing
 - Interior Features
 - Cast Iron







Planners Builders



Aesthetic, Iconic, Adaptable





Within the Context of Downtowns

- Downtown Anchor Architectural, Commercial, Historical and Cultural
- Important to local community
- Mixed Use Plan -Promotes diversity
- Often include Public Spaces
- Improve Accessibility
- Social Impacts place-making, public space
- Financial Resiliency of fully rented building








Architects Planners Builders

Downtown Anchor - Architectural, Commercial, Historical and Cultural



Taking advantage of the Brooks House location in center of Brattleboro





Architects Planners Builders

Important to local community



Standing room only ribbon cutting - Local investment in many ways





- Mixed Use Plan diversity is resilient
- Added Public Spaces
- Improved Accessibility
- Social Impacts place-making, public space



Commercial, educational, residential and public





Builders

Financial Resiliency of fully rented building



Anchor tenants with long term leases





Planners Builders

Important Features- Exterior



UVM Alumni House





"Architects Planners Builders

Exterior Wood Restoration






Brooks House-Replacement of elements only where necessary

'Architects Planners Builders

Exterior Wood Restoration



Brooks House- Reuse of material in good condition



Spanish cedar custom trim to match existing





Architects Planners Builders

• Exterior Brick Restoration





Brooks House- Terra cotta and brick rework



"Architects Planners Builders

Exterior Restoration



Town of Hartford- Recreation of dormers, restoration of existing brick



Architects Planners Builders

Exterior Restoration









Architects Planners Builders

Exterior Restoration















Planners Builders

• Exterior Restoration













Builders

Interior Features



UVM Alumni House- Important original interior features throughout







Interior Features





Town of Hartford- Highlighting Reused material previously on exterior





Planners Builders

Interior Features



Brooks House- Interior of Atrium



Planners Builders

Interior Restoration

















"Architects Planners Builders

Interior Restoration












Planners Builders

Interior Restoration















Challenge #3: Life Safety and ADA Improvements

- Requirements for Modern Code
 - Egress
 - Wall and Floor Assembly
 - Different Floor to Floor Use
 - Life Safety
 - Structural Upgrades



- Challenges-
 - Corridors, Stair, Elevator, Public Access
 - Separations and Sound Issues
 - Fire Protection During Construction
 - Upgrades to Fire Protection
 - Structural Work



Planners Builders

- Requirements for Modern Code
 - Egress/ADA/Elevator









Planners Builders

- Requirements for
- Modern Code



Egress










Planners Builders

- Requirements for
- Modern Code
 - Egress










- Requirements for Modern Code
 - Life Safety



Fire Resistance in multi-level, multi-use building: Brooks House

- Fire Alarm
- Smoke and heat detection
- Wet System Sprinkler
- Floor to floor and use to use Fire separation
- Smoke evacuation system in atrium
- Fire glass and window wash in certain areas
- Magnetic hold opens for specific doors
- 2 hour rated walls for all chases through floors





Architects Planners Builders



Smoke evacuation openings in atrium



Increased fire rated assemblies above ceiling between apartments



Builders



Fire rated assembly at all structure



Window wash sprinklers at 1st floor





Planners Builders



Egress doors at end of atrium corridor double as smoke exhaust





"Architects Planners Builders





Exit doors with special operators serve as intake louvers for smoke exhaust





Planners Builders



New Fire alarm panels at main entry





Challenge #4: Energy Efficiency Improvements

- Requirements to meet/exceed energy code
 - Envelope Upgrades
 - New HVAC systems/ Lighting and Power
 - Windows
- Challenges-
 - Open vs. Closed Cell Insulation with existing walls
 - Added Roof Insulation
 - Heat Pumps and ERUs
 - Cooling Tower
 - Moisture control






Planners Builders

COLUMN BUILDING SCIENCES

This article was published in ASHRAE Journal, September 2014. Copyright 2014 ASHRAE. Posted at www.ashrae.org. This article may not be copied and/or distributed electronically or in paper form without permission of ASHRAE. For more information about ASHRAE Journal, visit www.ashrae.org.





PISORE 1 (LEFT) Hygrothermal Regions. From "Understanding Vapor Barriers" ASHRAE Journal, August 2004. You should worry about freeze-thaw in "Cold Climates" (or colder) that have "Moderate" (or higher) amounts of precipitation. Cold Climates are defined more precisely as IECC Climate Zone 5 or higher if you are a Yank, HOURE 2 (NERT). Rainfall, From "Moisture Control for Buildings" ASHRAE Journal, February 2002. Where it rains more buildings get wetter, Yup. Cold and rain, double yup.



PHOTO 1 Getting it Right: Classic building at University of Toronto "Romanesque." Look at all the drip edges—at roof edges, at window openings, between floors. Notice that they are working. How can you tall? No stains. Look at this building carefully because it is an example of "what is good."

"Linings Add Warmth..."*

Tailor Made

BY JOSEPH W. LSTIBUREK, PH.D., P.ENG., FELLOW ASHRAE

How do you insulate uninsulated masonry buildings on the inside? Carefully. There I go again with the obvious. It is trickier to do it on the inside. But it is often less expensive than insulating them on the outside. True, you give



PROTO 2 Getting it Wrong, Look at the stains. Large expanses of glass don't absorb water and water nurs down them and ends up at comers that are typically "inset" with surfaces that don't slope. It gets worse, the windows themselves leak. Look at the bottom of the mullions where they meet the all.


Weighing building science and efficiency upgrades vs. historic preservation and architecture





Architects Planners Builders

PHOTO 3 (LETT) Getting It Wrong Continued. New building not yet acrewed up but going to get there soon. We can do better than this. This is obviously a new building but the style comes directly from Frank Lloyd Wright. Frank Lloyd Wright was wrong. PHOTO 4 (RIGHT) Getting It Wrong Turning into Ugly. Efforescence and freeze-thaw damage occurring and the cause is a combination of bad water control and bad brick. Could good brick have survived the bad water control? Maybe. But with good water control even the bad brick would have lived.






Building analysis: dewpoint and vapor migration in masonry structures





Planners Builders



Building sections for envelope analysis



Planners Builders

Stanislaus Building Science

2010-05-06 West Rutland Catholic School Insulation Retrofit Durability Risk Assessment



Figure 11: Interior view of floor beam from basement



Figure 13: Removed foundation stone on SW side



Figure 12: Moisture content measurement of beam



Figure 14: End view of floor joist, showing placement





Builders

Stanislaus Building Science Cooking in the kitchen

2010-05-06 West Rutland Catholic School Insulation Retrofit Durability Risk Assessment



Figure 23: Liquid water uptake testing



Figure 24: Drying of samples, for dry mass/density



Architects Planners Builders

- Requirements to meet/exceed energy code
 - Envelope Upgrades















Planners Builders

Thermal Envelope Improvements



Open cell and Closed cell spray foam at Brooks House





Builders

• Thermal Envelope Improvements



Brooks House: Closed cell at ceilings and wood framed walls. Roof also included continuous rigid insulation





Planners Builders

Thermal Envelope Improvements



Brooks House: Sound insulation floor to floor





"Architects Planners Builders

Thermal Envelope Improvements











Thermal Envelope Improvements





UVM Alumni house- envelope analysis





Planners Builders

• Thermal Envelope Improvements





UVM Alumni house





Builders

Thermal Envelope Improvements



Town of Hartford: Quest for net-zero. Building analysis revealed masonry cavity in walls





Architecto Planners Builders

• Thermal Envelope Improvements

		Marine al access					Curtain Wall			lu and add an	1	
	Dana Friisitaa	Windows		ı			Curtain Wali			Insulation	l	
	Base Exisitng Building	Run # 1 New Base	Run # 2	Run #3	Run # 4	Run # 5	Run # 6	Run # 7	Run # 8	Run # 9	Run # 10	Run # 11
Item		New base			Kull#4							
	Masonary, No		4" Foam, top 4' R-	, ,		4" Foam, top 4' R-		4" Foam, top 4' R-			, · · ·	4" Foam, top 4' R
Basement Walls	insualtion R-2	4" Foam, top 4' R-22	22	22	4" Foam, top 4' R-22	22	22	22	4' R-22	R-22	R-22	22
	Communica No.	Concrete no	Concrete no	Concrete no	Concrete no	Concrete no	Concrete no	Concrete no	Comments	Concrete no	Concrete no	Concrete no
	Concrete, No								Concrete no			
Basement Slab	insualtion R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1
		8" mineral fiber R-	O" minaral fiber D	O" minaral fiber D		Concrete no	Concrete no	Concrete no	Concrete no	Concrete no	Concrete no	Concrete no
Fire Floor	No Insulation	30	30		8" mineral fiber R-30	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1	inusation R-1
First Floor	NO ITISUIALIOII	30	30	30	o Illilleral liber K-50	IIIUSatioii K-1	IIIUSatioii K-1	IIIUSatioii K-1	IIIuSation K-1	IIIUSation K-1	IIIUSation K-1	IIIuSation K-1
									6"water	6"water blown		
	Brick, No	5"water blown	5"water blown	5"water blown	5"water blown spray	5"water blown	6"water blown	6"water blown	blown sprav		F"water blown	6"water blown
NAZ - 11 -	. , .	spray foam R-30		spray foam R-30	foam R-30	spray foam R-30			foam R-30			
Walls	insuation R-4	spray roam K-30	spray foam R-30	spray roam K-30	Toam K-30	spray roam K-30	spray roam K-30	spray foam R-30	TOam K-30	30	spray roam K-30	spray foam R-30
	Batts + misc. R-10 to R-30 on attic	8" spray foam in	8" spray foam in	8" spray foam in	8" spray foam in	8" spray foam in	9" caray foam in	8" spray foam in	9" spray foam	9" caray foam	10" spray foam	10" cpray foam
Roof / Attic	floor	rafters R-40	rafters R-40	rafters R-40	rafters R-40	rafters R-40	rafters R-40		in rafters R-40	in rafters R-40		in rafters R-40
Air Leakage	High	Very Low	Very Low	Very Low	Very Low	Very Low	Very Low	Very Low	Very Low	Very Low	Very Low	Very Low
All Leakage	Tilgii	very Low	Very LOW	Very LOW	very Low	Very LOW	very Low	Very LOW	Andy please	Very LOW	Very LOW	Very LOW
									put in the			
									best			
							Kwanaar Tri Fah	Kwaneer TriFab	performing	Kwaneer	Kurana ar TriΓah	Kwaneer TriFab
							VG451T 2"x4.5"	VG451T 2"x4.5"	curtian wall		VG451T 2"x4.5"	
							w/I" insulated	w/Alpin 925	description	2"x4.5" w/ I"		w/I" insulated
Fratorio Malall	N/A	xxx	xxx	xxx	xxx	xxxx	glass	insulated glass	for this run	insulated glass	glass	glass
Entry Curtain Wall	IN/A	***	***	***	***	Marvin Ultimate /	giass	maulateu gidss	ioi tilis tull	msulateu glass	grass	giass
						Magnum Double						
					Marvin Ultimate /	Hung triple	Fixed over	Fixed over	Fixed over	Fixed over	Fixed over	Fixed over
		Fixed over Awning	Double Hung	Marvin Integrity	Magnum Fixed over	glaszed krypton	Awning Listed	Awning Listed R-		Awning Listed	Awning Listed	Awning Listed
	Double Hung/		· ·	· ,	ŭ	· /·			_	- C		J
14/5	Double Hung w/	Listed R-9.1/R-6.7 Alpin 925	Listed R-5 Alpin 725	Double Hung Listed R-3.33	Awning Listed R- 3.57???	argon Listed R- 4.34???	R-9.1/R-6.7	9.1/R-6.7 Alpin 925	R-9.1/R-6.7	R-9.1/R-6.7	R-9.1/R-6.7	R-9.1/R-6.7
Windows	storm R-1.7	Aipin 925	/25	K-3.33	3.5/111	4.34111	Alpin 925	925	Alpin 925	Alpin 925	Alpin 925	Alpin 925





Builders

Thermal Envelope Improvements



Town of Hartford





Architect Planners Builders

• Thermal Envelope Improvements



Town of Hartford





"Architects Planners Builders

• Thermal Envelope Improvements



Town of Hartford





Architects Planners Builders

Thermal Envelope Improvements



Arthur's





Architects Planners Builders

• Thermal Envelope Improvements



Stanislaus





Architects Planners Builders

Thermal Envelope Improvements



Stanislaus





Architects Planners Builders

• Thermal Envelope Improvements



Stanislaus





Architects Planners Builders

Thermal Envelope Improvements



Watkins School





Architects Planners Builders

- Requirements to meet/exceed energy code
 - Windows





Brooks House- Windows





- Requirements to meet/exceed energy code
 - Windows



UVM Alumni House- windows





Planners Builders

- Requirements to meet/exceed energy code
 - Windows





Town of Hartford- Windows





- Arthur's Requirements to meet/exceed energy code
 - Windows







Watkins School - Windows






- Stanislaus Requirements to meet/exceed energy code
 - Windows







- Stanislaus Requirements to meet/exceed energy code
 - Windows









Planners Builders

Requirements to meet/exceed energy code





Watkins School - Windows





Mechanical, Electrical, Plumbing and Fire Protection Upgrades



Brooks House- High efficiency boilers

- High efficiency boilers
- Heat pump system utilizes excess heat and cooling
- Energy Recovery Units
- Digital Control System
- High Efficiency Lighting
- Sprinkler, Fire Alarm, Smoke exhaust system
- New wireless, cable, phone and data infrastructure





Builders

• Mechanical, Electrical, Plumbing and Fire Protection Upgrades



Infrastructure improvements





Builders

- Requirements to meet/exceed energy code
 - New HVAC systems



Town of Hartford- Air to Air Heat Pump System





Architects Planners Builders

Mechanical, Electrical, Plumbing and Fire Protection Upgrades



Town of Hartford- Air to Air Heat Pump System






Architects Planners Builders

- Requirements to meet/exceed energy code
 - New domestic solar hot water













Builders

- Stanislaus Requirements to meet/exceed energy code
 - New HVAC systems









'Architects Planners Builders

- Stanislaus Requirements to meet/exceed
- energy code
 - New HVAC systems

















Watkins School - Slate





Workshop Recap:

- Introduction
- Challenge #1- Overcoming Disaster
- Challenge #2- Meeting Preservation
 Standards
- Challenge #3- Life Safety and Building Access
- Challenge #4- Energy Efficiency
- Conclusions and Questions



THANK YOU!






Architects Planners Builders

















Planners Builders



Brooks House Atrium after completion







Brooks House- Duo Restaurant







Brooks House- Apartment







Brooks House- Storefront on Main Street





Architects Planners Builders



Arthur's







Stanislaus







Watkins School - Apartment